

Case Study

AUTOMOTIVE DEALERSHIP (BILL ESTES)

BACKGROUND

Bill Estes Chevrolet has been a VASEY service and project customer for 20+ years.

PROBLEM

Over the years, the dealership has made various changes to their facility. By eliminating a large awning and removing window tint from their showroom windows a significant increase in heat load was created.

SOLUTION

Due to a long-term relationship with the Bill Estes, VASEY volunteered to redesign the duct work and make modifications to the existing system to accommodate the dealer's changes.



END RESULT

VASEY revamped the duct work, relocated grills and diffusers and enlarged the ductwork for increased air flow at no cost to the dealership. This was certainly a plus for future heating and cooling upgrades and revisions. At VASEY we strive to go above and beyond the norm, and we stand behind our products and our services.

